

# HS-AS Studs

adapters



Adapters to connect accelerometers to machine faces.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

| Part No.    | Connection Point 1         | Connection Point 2 |
|-------------|----------------------------|--------------------|
| HS-AS006    | Quick Fit Female           | 1/4"-28 UNF Male   |
| HS-AS009    | M6 Female                  | M8 Male            |
| HS-AS026    | 10-32 UNF Male             | M6 Male            |
| HS-AS028    | Quick Fit Female 1/2" UNC  | 1/4"-28 UNF Male   |
| HS-AS030    | M8 x 1.25 Female           | 1/8"BSPT Male      |
| HS-AS032    | Quick Fit Female           | M8 Male            |
| HS-AS039    | Quick Fit Female 1/2" UNC  | 10-32 UNF Male     |
| HS-AS045    | Quick Fit Female           | M5 Female          |
| HS-AS088    | Quick Fit Female 9/16" UNC | M5 Female          |
| HS-AS092    | 3/8" UNF Female            | 3/8" NPT Male      |
| HS-AS103    | 1/4"-28 UNF Female         | 1/4" NPT Male      |
| HS-AS107-M6 | M6 Female                  | M6 Male            |
| HS-AS111    | M8 Female                  | M8 Female          |
| HS-AS119    | 1/4"-28 UNF Female         | 1/4"-28UNF Male    |
| HS-AS121    | 1/4"-28 UNF Female         | 3/8"-16 UNC Male   |

